ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra

Street ID	Street Name	Significant Landmark
W0127, W0074, W0082, W0117, W0119, W0066, W0125, W	NA, Veera Anjaneya Temple Rd	HegadeNagara near arch

Segment No.	Total Length (m)
6/C-W0127/S045226	202.39

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	90.45	77.637073	13.072609	77.637088	13.073426	W0074	W0066
2	27.62	77.637030	13.072549	77.637022	13.072300	W0074	DEAD END
3	84.32	77.636738	13.071624	77.636695	13.070863	W0085	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to Roads and Drains at Hegade Nagara in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	2000000	2016

Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	

Tender	Work Details	Job No. / Work Code
Not a Tender	Improvement to Roads and Drains at Hegade Nagara in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-16-000033

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/95/2016-17	05/08/2016	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
05/08/2016	04/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL BANGALORE		0.00

Phone No.	E-Mail ID
9449863065	

Field Inspection Details

Number of Trees	Any Other Information	Name
4		KRISHNAPPA

Date of Inspection	Remarks
31/10/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0127, W0074, W0082, W0117,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	31/10/2016	30/11/2016	COMPLETED
SE	VASU K M	31/10/2016	30/11/2016	COMPLETED
EE	YARAPPA REDDY	31/10/2016	30/11/2016	COMPLETED
AEE	J N LOKESH	31/10/2016	30/11/2016	COMPLETED
AE	KRISHNAPPA	31/10/2016	30/11/2016	COMPLETED
AE	KRISHNAPPA	31/10/2016	30/11/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0127, W0074, W0082, W0117,